

CARDAN LABORATORIES, INC.  
PO BOX 541  
634 14TH STREET  
NORTHERN CAMBRIA, PA 15714-0541  
PH: 814-948-8650 FAX: 814-948-5893  
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.  
DEP CERTIFICATION 11-139

06/03/2016

PATTON BORO  
P.O. BOX 175  
  
PATTON, PA 16668

LABORATORY NUMBER: 5064

SOURCE: 800 4TH AVE. ID #704

SAMPLED BY: KRT      DATE SAMPLED: 06/01/2016 09:00  
DATE REC'D...: 06/01/2016 12:05

B A C T E R I O L O G I C A L   E X A M I N A T I O N

DATE STARTED: 06/01/2016 15:30      ANALYST: SS  
DATE ENDED...: 06/02/2016 15:30      ANALYST: SS

TOTAL COLIFORM - MEMBRANE FILTRATION

TOTAL COLIFORM (M-ENDO AT 35.0 DEGREES C. FOR 24 HRS)

VOLUME OF SAMPLE: 100 ML

TOTAL COLIFORM: ABSENCE  
METHOD: SM9222B

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,  
except if noted in this report.

CARDAN LABORATORIES, INC.

BY: *Scott Semelberger*

CARDAN LABORATORIES, INC.  
PO BOX 541  
634 14TH STREET  
NORTHERN CAMBRIA, PA 15714-0541  
PH: 814-948-8650 FAX: 814-948-5893  
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.  
DEP CERTIFICATION 11-139

06/10/2016

PATTON BORO  
P.O. BOX 175  
PATTON, PA 16668

LABORATORY NUMBER: 5093

SOURCE: ID #703

SAMPLED BY: KRT DATE SAMPLED: 06/08/2016 10:00  
DATE REC'D...: 06/08/2016 11:50

B A C T E R I O L O G I C A L E X A M I N A T I O N

DATE STARTED: 06/08/2016 13:05 ANALYST: SS  
DATE ENDED...: 06/09/2016 13:00 ANALYST: SS

TOTAL COLIFORM - MEMBRANE FILTRATION

TOTAL COLIFORM (M-ENDO AT 35.0 DEGREES C. FOR 24 HRS)

VOLUME OF SAMPLE: 100 ML

TOTAL COLIFORM: ABSENCE  
METHOD: SM9222B

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,  
except if noted in this report.

CARDAN LABORATORIES, INC.

BY:

*Scott Semelberger*

CARDAN LABORATORIES, INC.  
PO BOX 541  
634 14TH STREET  
NORTHERN CAMBRIA, PA 15714-0541  
PH: 814-948-8650 FAX: 814-948-5893  
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.  
DEP CERTIFICATION 11-139

06/20/2016

PATTON BORO  
P.O. BOX 175  
PATTON, PA 16668

LABORATORY NUMBER: 5102

SOURCE: (LEAK) SPECIAL SAMPLE

SAMPLED BY: KRT      DATE SAMPLED: 06/13/2016 12:40  
DATE REC'D.: 06/13/2016 13:10

B A C T E R I O L O G I C A L   E X A M I N A T I O N

DATE STARTED: 06/13/2016 13:30      ANALYST: SS  
DATE ENDED.: 06/14/2016 13:30      ANALYST: SS

TOTAL COLIFORM - MEMBRANE FILTRATION

TOTAL COLIFORM (M-ENDO AT 35.0 DEGREES C. FOR 24 HRS)

VOLUME OF SAMPLE: 100 ML

TOTAL COLIFORM: ABSENCE  
METHOD: SM9222B

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,  
except if noted in this report.







CARDAN LABORATORIES, INC.  
PO BOX 541  
634 14TH STREET  
NORTHERN CAMBRIA, PA 15714-0541  
PH: 814-948-8650 FAX: 814-948-5893  
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.  
DEP CERTIFICATION 11-139

06/20/2016

PATTON BORO  
P.O. BOX 175  
PATTON, PA 16668

LABORATORY NUMBER: 5113

SOURCE: ID 702

SAMPLED BY: MP DATE SAMPLED: 06/15/2016 09:00  
DATE REC'D...: 06/15/2016 12:00

B A C T E R I O L O G I C A L E X A M I N A T I O N

DATE STARTED: 06/15/2016 13:15 ANALYST: SS  
DATE ENDED...: 06/15/2016 13:15 ANALYST: SS

TOTAL COLIFORM - MEMBRANE FILTRATION

TOTAL COLIFORM (M-ENDO AT 35.0 DEGREES C. FOR 24 HRS)

VOLUME OF SAMPLE: 100 ML

TOTAL COLIFORM: ABSENCE  
METHOD: SM9222B

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,  
except if noted in this report.