CARDAN LABORATORIES, INC.

PO BOX 541 634 14TH STREET NORTHERN CAMBRIA, PA 15714-0541 PH: 814-948-8650 FAX: 814-948-5893 Coal, Water, Gas, Rock, Dust, Mine Air, Etc. DEP CERTIFICATION 11-139

11/11/2016

PATTON BORO P.O. BOX 175

PATTON, PA 16668

LABORATORY NUMBER: 5393

SOURCE:

DATE SAMPLED: 11/09/2016 10:00 DATE REC'D..: 11/09/2016 11:50 SAMPLED BY: MP

BACTERIOLOGICAL EXAMINATION

DATE STARTED: 11/09/2016 15:30 DATE ENDED..: 11/10/2016 15:30 ANALYST: SS ANALYST: SS

TOTAL COLIFORM - MEMBRANE FILTRATION

TOTAL COLIFORM (M-ENDO AT 35.0 DEGREES C. FOR 24 HRS)

VOLUME OF SAMPLE: 100 ML

TOTAL COLIFORM: ABSENCE

METHOD: SM9222B

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder, except if noted in this report.

CARDAN LABORATORIES, INC.

Sut Semellarger