

CARDAN LABORATORIES, INC.
PO BOX 541
634 14TH STREET
NORTHERN CAMBRIA, PA 15714-0541
PH: 814-948-8650 FAX: 814-948-5893
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.
DEP CERTIFICATION 11-139

06/09/2017

PATTON BORO
P.O. BOX 175

PATTON, PA 16668

LABORATORY NUMBER: 5761

SOURCE:

SAMPLED BY: MP DATE SAMPLED: 06/07/2017 09:00
 DATE REC'D...: 06/07/2017 11:50

B A C T E R I O L O G I C A L E X A M I N A T I O N

DATE STARTED: 06/07/2017 13:30 ANALYST: SS
DATE ENDED...: 06/08/2017 13:30 ANALYST: SS

METHOD: SM9223B

* * * * * R E S U L T S * * * * *

	DATE	TIME	ANALYST
TOTAL COLIFORM: ABSENT	06/08/2017	13:30	SS
E-COLI.....: ABSENT	06/08/2017	13:30	SS

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,
except if noted in this report.

CARDAN LABORATORIES, INC.

BY: Daniel R. Antos