

CARDAN LABORATORIES, INC.  
PO BOX 541  
634 14TH STREET  
NORTHERN CAMBRIA, PA 15714-0541  
PH: 814-948-8650 FAX: 814-948-5893  
Coal, Water, Gas, Rock, Dust, Mine Air, Etc.  
DEP CERTIFICATION 11-139

06/16/2017

PATTON BORO  
P.O. BOX 175

PATTON, PA 16668

LABORATORY NUMBER: 5779

SOURCE:

SAMPLED BY: MP      DATE SAMPLED: 06/14/2017 09:00  
                                    DATE REC'D...: 06/14/2017 11:45

B A C T E R I O L O G I C A L   E X A M I N A T I O N

DATE STARTED: 06/14/2017 14:05      ANALYST: SS  
DATE ENDED...: 06/15/2017 14:05      ANALYST: SS

METHOD: SM9223B

\* \* \* \* \* R E S U L T S \* \* \* \* \*

	DATE	TIME	ANALYST
TOTAL COLIFORM: ABSENT	06/15/2017	14:05	SS
E-COLI.....: ABSENT	06/15/2017	14:05	SS

THIS TEST HAS INDICATED THAT THIS WATER IS ACCEPTABLE.

No problems were encountered during analysis of this workorder,  
except if noted in this report.

CARDAN LABORATORIES, INC.

BY:

*Scott Senchler*